



DUTCH
SAFETY BOARD

Runway excursion after loss of thrust at low speed



Runway excursion after loss of thrust at low speed

Limited review by Harry Horlings, AvioConsult.
Lt-Col RNLAF ret., graduate FTE USAF Test Pilot School.

For higher resolution images refer to the original report:
<https://www.onderzoeksraad.nl/en/page/4875/runway-excursion-maastricht-aachen-airport-11-november-2017>

The title page is not i.a.w. Annex 13, App 1:

Name of the operator; manufacturer, model, nationality and registration marks of the aircraft; and place and date of the accident or incident.

The Hague, March 2020

The reports issued by the Dutch Safety Board are open to the public and available on www.safetyboard.nl.

Cover photo: Aviation police

The Dutch Safety Board

NL committed to ICAO Annex 13, isn't it?
Objective of the ICAO is that also other countries
can learn from accidents and incidents.

When accidents or disasters happen, the Dutch Safety Board investigates how it was possible for these to occur, with the aim of learning lessons for the future and, ultimately, improving safety in the Netherlands. The Safety Board is independent and **is free** to decide which incidents to investigate. In particular, it focuses on situations in which people's personal safety is dependent on third parties, such as the government or companies. In **certain cases** the Board is under an **obligation** to carry out an investigation. Its investigations do not address issues of blame or liability.

ICAO Annex 13 is about investigating aircraft accidents and incidents; § 5.1: The State of Occurrence **shall** institute an investigation into the circumstances of the accident and **be responsible** for the conduct of the investigation.
ICAO Doc 9756 Part IV - Reporting: The sole objective of the investigation and the Final Report is the prevention of accidents and incidents.
The Netherlands is a contracting State.

Dutch Safety Board

Chairman: J.R.V.A. Dijsselbloem
M.B.A. van Asselt
S. Zouridis

Secretary Director: C.A.J.F. Verheij

Visiting address: Lange Voorhout 9
2514 EA The Hague
The Netherlands

Postal address: PO Box 95404
2509 CK The Hague
The Netherlands

Telephone: +31 (0)70 333 7000

Website: safetyboard.nl

E-mail: info@safetyboard.nl

N.B. This report is published in the English language with a separate Dutch summary. If there is a difference in interpretation between the report and the summary, the report text will prevail.

Abbreviations	5
General overview	8
Summary	9
1 Factual information	10
1.1 History of the flight.....	10
1.2 Injuries to persons.....	12
1.3 Damage to aircraft.....	12
1.4 Other damage.....	12
1.5 Personnel information.....	13
1.6 Aircraft information.....	14
1.7 Meteorological information.....	14
1.8 Communications.....	14
1.9 Aerodrome information.....	15
1.10 Flight recorders.....	15
1.11 Wreckage and impact information.....	18
1.12 Tests and research.....	19
1.13 Organizational and management information.....	20
1.14 Additional information.....	25
2 Investigation and analysis	27
2.1 General.....	27
2.2 The flight and the occurrence.....	28
2.3 Asymmetric thrust.....	34
2.4 Engine failure.....	34
2.5 Noise cancelling headsets.....	35
2.6 The startle effect.....	35
3 Findings and conclusion	38
3.1 Findings.....	38
3.2 Conclusion.....	39
Appendix A. Transcript	40
Appendix B. Engine examination	43

ABBREVIATIONS

AGB	Accessory Gear Box	Why is AFM (Airplane Flight Manual) missing here and in the report? It is the only document approved by airworthiness authorities for operating the airplane. Refer to the FAA Type Certificate Data Sheet.
AMM	Aircraft Maintenance Manual	
ASDA	Accelerate Stop Distance Available	
ATC	Air Traffic Control	
ATIS	Automatic Terminal Information Service	
ATOW	Actual Take-off Weight	Is this abbrev. used by Boeing? Not TOGW?
ATP	Acceptance Testing Procedure	
ATPL(A)	Airline Transport Pilot License (aeroplane)	
BKN	Broken	
BSCU	Brake System Control Unit	Is not used without explanation, and only once in this report, why in this list? Concerns more abbreviations.
CG	Centre of Gravity	
CMM	Component Maintenance Manual	
CRM	Crew Resource Management	
CSN	Cycles Since New	
CVR	Cockpit Voice Recorder	
DEP	Departure	
DEST	Destination	
DOW	Dry Operating Weight	You mean Zero Fuel Weight? Is DOW used in B747 manuals?
EGT	Exhaust Gas Temperature	
EHBK	Maastricht Aachen Airport	
EPR	Engine Pressure Ratio	
FADEC	Full Authority Digital Engine Control	
FAR	Federal Aviation Regulations	
FCOM	Flight Crew Operations Manual	
FCTM	Flight Crew Training Manual	
F/D	Flight Director	
FDR	Flight Data Recorder	
FL	Flight Level	
FOD	Foreign Object Damage	
Ft	Feet	
GE	General Electric	
HPa	Hectopascal	hPa - is a symbol, not an abbreviation.
HPC	High Pressure Compressor	
HPT	High Pressure Turbine	

ICAO	International Civil Aviation Organization
IR(A)	Instrument Rating (Aeroplane)
KNMI	Dutch Meteorological Office
LE	Leading Edge
LH	Left Hand
LPC	License Proficiency Check
LPT	License Proficiency Training
METAR	Meteorological Aerodrome Report
MSL	Mean Sea Level
MTOW	Maximum Take-Off Weight
N1	The rotational speed of the low speed <u>spool</u> of an engine, expressed as a percentage of a nominal value
NM	Nautical Mile
NTSB	National Transportation Safety Board (USA)
OEJN	King Abdulaziz International Airport
OM	Operations Manual
OPC	Operator Proficiency Check
OPT	Operator Proficiency Training
OVC	Overcast
PF	Pilot Flying
PM	Pilot Monitoring
PW	Pratt and Whitney
QRH	Quick Reference Handbook
RR	Rolls Royce
RTO	Rejected Take-Off
SIGMET	Significant Meteorological Information
SMS	Safety Management System
SOP	Standard Operating Procedures
TAF	Terminal Aerodrome Forecast
TO/GA	Take-off/Go-around
TODA	Take-Off Distance Available
TORA	Take-Off Runway Available
TOW	Take-Off Weight
TR	Trainee
TRA	Throttle Resolver Angle
TRI	Type Rating Instructor
TSN	Time Since New

ICAO airport code of
Why in this list?

A takeoff can be rejected before it begins, it is aborted when it began (Dictionary of the English Language). Even native English speakers make this mistake. Do not copy mistakes.

UTC	Coordinated Universal Time (Greenwich mean time)
VBV	Variable Bleed Valve
V _{MCG}	Minimum control speed of an aeroplane on ground
VSV	Variable Stator Vane

the

ICAO recommends to use abbreviations out of its Reporting Manual only, and only those that are used in the report:
Doc 9756 Part IV, Appendix 3 to Chapter 1.

GENERAL OVERVIEW

??

Identification number:	2017118
Classification:	Serious incident
Date, time of occurrence:	11 November 2017, around 22.36 hours ¹
Location of occurrence:	Maastricht Aachen Airport (EHBK)
Registration:	TC-ACR
Aircraft type:	Boeing 747-400 ERF
Aircraft category:	Aeroplane
Type of flight:	Commercial cargo flight
Phase of operation:	Take-off
Damage to aircraft:	Substantial
Flight crew:	Two (captain and first officer)
Other crew:	Two (technician and load master)
Passengers:	None
Injuries:	None
Other damage:	Deep tracks made by the landing gear in the soft ground of the airfield
Light conditions:	Darkness

¹ All times are UTC, unless otherwise specified. Local time is UTC+1 hour.

SUMMARY

TC-ACR, a Boeing 747-400 ERF, was scheduled to make a cargo flight from Maastricht Aachen Airport in the Netherlands to King Abdulaziz International Airport in Jeddah. After the aircraft was loaded, the captain, who was pilot flying, taxied to Runway 21 and initiated a rolling take-off. He advanced the thrust levers and, when the engines had stabilised, he pushed the TO/GA switches, causing the engines to accelerate to the selected take-off thrust. The aircraft had accelerated to approximately 30 knots when the outboard engine on the right side (engine #4) suddenly lost power. The aircraft veered to the right due to the resultant asymmetric thrust. The thrust levers were not immediately retarded to idle, so this asymmetric thrust continued. Attempts to steer the aircraft back to the centreline by means of nose wheel steering and differential braking, were unsuccessful. The aircraft could not be controlled. It veered off the runway and continued on into the soft ground on the right-hand side of the runway. The resistance of the soft ground and the eventual retardation of the thrust levers caused the aircraft to come to a standstill. None of the crew was injured. The aircraft sustained substantial damage. The runway excursion was caused by prolonged asymmetric thrust, due to the loss of thrust on engine #4 at low speed. The loss of engine thrust was caused by a compressor stall.

drag

Of course, airplane not designed to be able to steer back to CL at airspeed below V_{MCG} while high asymmetrical thrust levels set. Rewrite this line.

by definition (because thrust was not reduced by pilot).

The only way to arrest a deviation resulting from asymmetric thrust below the speed at which the rudder becomes effective, is to promptly retard the thrust levers to idle. That has not happened in this occurrence; it took about eight seconds for the thrust levers to be retarded. Not retarding the thrust levers was most likely due to the 'startle effect' on the crew. The startle effect caused the crew to deviate from standard procedures. The use of noise cancelling headsets could also have played a role in this scenario.

below the min. control speed V_{MCG} / below V_1 .

$V_1 = V_{MCG} + \text{two increments.}$

Sure? No, all crew expect this

Following the loss of thrust on engine #4, the crew did not respond as they had been trained for and their actions were not in accordance with the RTO procedures described in the manuals. Flight crews are trained to deal with unexpected rejected take offs due to an engine failure. However, the element of surprise in training in a simulator setting is very limited. The flight crews are aware that a failure is about to occur. This greatly diminishes the element of surprise during simulator sessions. As a result, the chance that the 'startle effect' occurs during the training is minimal.

loss of thrust was a

not always, not every takeoff

The cause of the compressor stall has not been extensively investigated. However, some engine components have been examined. While some of them clearly needed to be overhauled as a result of wear (due to the age of the engine), none of them could be linked to the compressor stall. The compressor stall might have been a result of the overall technical state of the engine.

conduct (they reject / abort themselves - is pilot action)

Bad summary. Refer to Annex 13, Appendix 1, and ICAO Doc 9756 Part IV - Reporting

Reject is not used correctly. A takeoff can be rejected before it begins, it is aborted when it began (Dictionary of the English Language).

1 FACTUAL INFORMATION

1.1 History of the flight

On Saturday 11 November 2017, the aircraft, a Boeing 747-400 ERF with the registration number TC-ACR was parked on cargo apron B at Maastricht Aachen Airport (EHBK). The aircraft was scheduled to depart at 21.55 hours to make a cargo flight (SV916) to King Abdulaziz International Airport in Jeddah (OEJN). The crew consisted of a captain, a first officer, a technician and a load master. The aircraft had arrived from Jeddah earlier that day, at 10.26 hours. According to the combined flight and technical log, no additional defects or anomalies were recorded during the inbound flight.

kg or lb normally used

FAA Approved Weight and Balance Control and Loading Manual?

The aircraft was refuelled with 57,753 litres of fuel. It was loaded with 85,110 kilograms of cargo, in accordance with the loading instruction report. The captain stated that he had felt unduly pressured, due to the night flight restrictions at EHBK. The handling agent had urged him to depart, as the airport was due to close at 22.00 hours. Despite the urgency of the situation, the captain first called the airline's Operations Department for consultation. As a result of this consultation and the granting of an exemption by the airport authorities extending the take-off deadline until 23.00 hours, the crew was ready for departure. The captain (pilot flying) was seated on the left side of the cockpit, the first officer (pilot monitoring) was seated on the right side, the technician was seated in the cockpit, in the observer's seat (behind the flight crew), and the load master was seated in the cabin area. The captain and the first officer were wearing their headsets and were communicating with one another via the intercom system. The first officer left one ear uncovered by the headset. The technician and the load master were not wearing headsets.

The flight crew performed the flight briefing and completed the pre-flight procedures. Around 22.19 hours, when all pre-flight preparations had been completed, the crew reported to Air Traffic Control (ATC) that they were ready for push back and requested clearance for departure.

Around 22.29 hours the aircraft was cleared for start-up. Once the pre-start checklist had been completed, the engines were started. All four engines took the same time to start up and gave identical indications during the start-up sequence. After the start-up, the engines stabilised at their normal values. Since Apron B is only around 300 metres from the start of Runway 21, the crew decided to complete both the before taxi checklist as well as the before take-off checklist before taxi commenced. The crew did not observe any anomalies at this time. According to FDR data, the normal engine warming-up criteria were met. ATC cleared the aircraft for taxi at 22.34 hours, after which TC-ACR taxied to Runway 21. During taxi, the crew made some remarks about how dark it was (the sky was

overcast so there was no moonlight, and there were few other sources of illumination). While taxiing to Runway 21, the aircraft was cleared for take-off at 22.35:35 hours.

? Takeoff briefing?

source?

After some general conversation between the captain and the first officer about the flight, the aircraft entered Runway 21 and a synthetic voice reported 'on Runway 21' at 22.36:26 hours. The aircraft maintained a groundspeed of 5 kts. Five seconds later, the first officer called 'Set thrust', after which the captain called 'Take off', at 22.36:32 hours. The captain advanced the thrust levers to approximately 70% N1 and the sound of engines spinning up was audible on the CVR. Once the engines had stabilised at around 70% N1, the captain pushed the TO/GA switches, causing the engines to accelerate to the selected take-off power. Meanwhile, the aircraft's ground speed was increasing. At 22.36:36 hours, the captain called 'Set take-off thrust'. Four seconds later, at around 22.36:40 hours, a loud noise was audible on the CVR. The first officer, the technician and the load master stated that they had heard a loud bang from outside the aircraft.

The flight crew was interviewed shortly after the incident. In his statement, the captain indicated that he had not heard the bang as he was wearing an active noise cancelling headset. The captain noticed that the aircraft was yawing to the right, but at that moment he did not know what was causing this. He attempted to correct this deviation, using the nose wheel steering tiller and by applying left rudder. He then applied the left-hand brake pedal. The aircraft moved a little to the left, but almost instantly resumed its deviation to the right. When the captain noticed that the aircraft was moving to the right side of the runway he concluded that it was uncontrollable. He then took the decision to abort the take-off, and applied both brake pedals. He stated that he immediately pulled the thrust levers back and held them, in case the autothrottle disconnect button failed to respond. In spite of these actions, the aircraft veered off the runway and rolled onto the grass. At 22.37:02 hours the engines were switched off. None of the four persons on board were injured.

moved? yawed? Where are all of these data?

? Can only be one cause - one cure: abort

The first officer had been monitoring the instruments during the take-off. He stated that he had not noticed any anomalies on the instruments. In his role as pilot monitoring, he was required to make the 80 kts call when the aircraft reached that speed. Therefore his attention was shifted from the engine instruments to the air speed indicator. When he heard the loud noise from the right side of the aircraft and noticed that the aircraft was veering to the right, he immediately called: 'Off, abort, abort, abort'. He stated that, while he did not know what had happened, he was convinced that the take-off had to be aborted. He also stated that he had not operated any control devices in an attempt to help the captain keep the aircraft on the runway.

at 36:41, 5 s after capt ordered Set takeoff thrust

Some witnesses on the ground heard a loud bang shortly after the start of the take-off roll. Since it was dark, nobody knew what had caused this noise.

The aircraft had veered off the runway and had come to a standstill in the soft soil of the grass field on the right side of Runway 21. After the occurrence, it was found that all of the aircraft's engines were in reverse and its speed brakes were up.

Not approved on B747 at low speed!

The next day, the aircraft was off-loaded and defueled. It was then recovered from the area of soft ground in which it had come to rest, and towed to a parking stand.



Figure 1: Aerial pictures of the runway excursion. (Source: Aviation police)

1.2 Injuries to persons

None.

1.3 Damage to aircraft

The aircraft sustained substantial structural damage as a result of the occurrence. This damage consisted of several bent and deformed skin panels and stringers. In addition, the nose wheel well web had several deformations on the right- and left-hand sides. As a result of this damage, the manufacturer of the aircraft had to carry out major repairs at Maastricht Aachen Airport.

nose landing gear wheel well

1.4 Other damage

Deep tracks left by the aircraft's gear in the soft ground of the airfield.

landing gears (a gear can be anything)

1.5 Personnel information

1.5.1 Captain

Age	63
Nationality	Turkish
License	ATPL(A), valid until 28 February 2018
Ratings	B-747 400, IR
Medical certificate	Class 1, valid until 2 March 2018
Total flight hours	18,550:40
Flight hours on type	3,030:50
Flight hours previous 30 days	79:42
Rest hours before the flight	55:59

1.5.2 First officer

Age	42
Nationality	Turkish
License	ATPL(A), valid until 31 January 2018
Ratings	B-747 400, IR, TRI
Medical certificate	Class 1, valid until 10 April 2018
Total flight hours	4,462:58
Flight hours on type	2,042:43
Flight hours previous 30 days	64:46
Rest hours before the flight	55:59

1.6 Aircraft information

Make and model	Boeing 747-400 ERF
Serial number	32866
Year of manufacture	2002
Airworthiness Review Certificate	Valid until 16 June 2018
Engines	4 GE CF6-80C2B5F
Engine #4	Ser.no. 706509, TSN 42,617.01, CSN 6,953
Weights and balance	DOW 160,902 kg, MTOW 412,769 kg ATOW 309,712 kg
	Index 53.4, CG 21.3%
Maintenance status	Airworthiness certificate valid until 16 June 2018
Deferred items	One item, non-relevant

ZFW,
BEW?

Are DOW and ATOW used by Boeing?
Don't believe so, are not standard.

Show diagram. How much weight
on the nose landing gear?

+ info on landing gears, span width main landing gears. Cargo & Fuel onload here rather than buried in § 1.1.
+ The takeoff thrust setting and other performance data? List of defects.

Are two different things

1.7 Meteorological information

The crew obtained relevant weather information from the ground handling staff. This consisted of updated reports (METAR), forecasts (TAF), significant weather charts (SIGMET) and wind charts for the flight. The prevailing weather conditions during the occurrence were as follows: wind direction 250 degrees (varying from 210 to 300 degrees) with a strength of 3 kts, visibility 8 kilometres, clouds broken at 4,000 ft and overcast at 4,400 ft, temperature 5 °C, dew point 5 °C, the local air pressure adjusted to mean sea level was 1011 hPa.²

hPa

QNH

1.8 Communications

All ATC communication was carried out by Maastricht Tower. The details of all relevant communications are included in the transcript (Appendix A) and in section 1.1.

1.8 Aids to Navigation. N/A
(maintain standard numbering)

CVR,
Was an ATC transcript
made?

The transcript cannot be
complete. Who determined
what was relevant?

² METAR EHBK 112225Z AUTO 25003KT 210V300 8000 BKN040 OVC044 05/05 Q1011.

1.9 Aerodrome information

Maastricht Aachen Airport has a single paved runway (03-21). The dimensions of this runway are 2,750 x 45 metres. Runway 21 has a displaced threshold of 250 metres. For large aircraft, such as the Boeing 747, the full length of the runway is available. ~~This gives a TORA/TODA/ASDA of 2,750 metres.~~ On each side of the runway there is an 8-metre-wide paved shoulder. Beyond these runway shoulders, there is soft soil with grass cover.

Elev above MSL? Jeppesen Chart?

for takeoff

The runway surface consists of anti-skid asphalt. Runway friction measurements are carried out on Runway 03-21 annually. The last measurement prior to the date of the occurrence was carried out on 27 November 2017. Several measurements were carried out with 1 mm water on the runway, at different speeds and at different distances from the centreline. According to the report, Runway 21 exceeded the minimum required friction levels under all these conditions. Around the time of the occurrence, the runway surface was damp.

B-Apron, the cargo platform, is situated near the threshold of Runway 21. It can be reached via taxiway W1. The distance from an aircraft stand on B-Apron to the threshold of Runway 21 is approximately 300 metres. Was the airplane indeed parked on this apron?

The airport's opening hours for cargo flights are 06.00 to 22.00 hours, from Monday to Sunday. The airport authorities can grant a one-hour exemption, commencing at 22.00 hours.

1.10 Flight recorders

1.10.1 Flight Data Recorder

Where is all of the FDR data? Include (part of) NTSB Factual Report, please

The aircraft was equipped with a solid-state flight data recorder (FDR), manufactured by Honeywell. Data from the FDR was successfully downloaded and verified. With the assistance of the aircraft's manufacturer, the following 'sequence of events' was created, based on FDR data.

This is analysis, is not expected here, but in chapter 2

Page 16

FDR data showed that the aircraft was configured for a flaps 20 take-off. The magnetic heading increased as the aircraft turned right from the taxiway onto Runway 21. At 22.36:24 hours the throttle resolver angles (TRAs) ~~were~~ increased from 40 to 43 degrees, after which the engines' N1 stabilised at around 42%. At 22.36:31 hours the TRAs ~~were~~ increased from 43 to 56 degrees. The engines' N1 increased from around 42% to 74%, and the longitudinal (forward) acceleration increased as the aircraft began its take-off roll. Beginning at 22.36:33 hours, a small amount of left rudder pedal pressure was applied. The TRAs ~~were~~ increased again, starting at 22.36:40 hours and the engine N1 and longitudinal acceleration began to increase. The N1 of all four engines increased, this was uniform for engines #1 to #3 but more rapid in the case of engine #4. When the N1 of engine #4 reached 92%, the N1 values for engines #1 to #3 were 81.6%, 82.8% and 87% respectively. Around this time, left pedal input was removed, and the right pedal was applied.

Not iaw page 32

and increasing.

So pedal was to the wrong side! Did the pilot steer the airplane off the runway?

Cause - effect. Engine #1 caused asymmetrical thrust, hence a yaw (heading increase). The nose gear friction on the runway was not adequate to counteract the asym thrust yawing moment that was sustained. The effect was that the airplane started to deviate to the right and vacated the runway. (Was this a sideward acceleration? Rubber of MLG on the asphalt? No acceleration in the lateral body axis). Accel on FDR?

Almost immediately after the TRAs were increased, at a ground speed of 30 knots and at 92% N1, there was a sudden drop in engine #4's N1 – yet the corresponding TRA had not been changed. Engine #4's N1 dropped to a value of around 20%, while the N1 of the other three engines remained at around 97%.

Was this the calculated N1?

? Where from?

The aircraft's lateral (sideways) acceleration to the right increased, and the magnetic heading also began to increase as the aircraft's course deviated to the right of the runway heading. Input to the right pedal was quickly discontinued, and full left pedal input was applied at 22.36:42 hours. The left pedal was briefly released, for an interval of one second, at 22.36:43 hours, before quickly being reapplied. At the same time, the control wheel was deflected slightly to the left.

Where are these data? Page 32.

Very unclear analysis, not in agreement with bottom line pag. 15. Rudder graph on page 32 has bad time scale.




Figure 2: Plot of FDR data (N1, TRA, T/R, GS). The vertical line indicates the moment at which engine #4's N1 dropped.

of all of them?

Where are these data?

At 22.36:44 hours, the main gear brake torque increased, and the aircraft's longitudinal acceleration began to decrease. Shortly after the initial application of the brake, the brake torques of the right body and wing gear decreased. Higher brake torques on the left wing and body gear, relative to the right, are indicative of differential braking.

Where are these data? What was the air-speed?

The aircraft's ground speed reached a maximum of 42 knots before it began to decrease. At 22.36:46 hours, the control wheel was momentarily deflected around 24 degrees to the left. The thrust levers were reduced to approximately forward idle at 22.36:48 hours. The remaining engines' N1 values began to drop, and the aircraft's longitudinal acceleration decreased. At 22.36:52 hours, at a ground speed of 19 knots, the main gear brake torques dropped to around zero. At 22.36:56 hours as the ground speed reached zero,

Sure ground speed? How did you get this?

why here not TRA?

What was N1? Fig 2 shows only N1 increase of #1. This is not approved at speeds below 60 kt.

the thrust levers transitioned to the reverse idle detent, causing the thrust reverser sleeves to transition to the in-transit state. The thrust reverser sleeves were fully deployed around 2 seconds later. At the same time, the deflection of the speed brake handle began to increase. The autothrottle had not been disconnected manually; instead it was automatically disconnected when the thrust reversers were selected.

manually? Did you review the switching logic?

lever

Ground Track Analysis

Using FDR data, the manufacturer prepared a ground track analysis. The results indicate that engine #4's N1 began to decrease 300 feet before the runway displaced threshold. Full left pedal was applied around 80 feet later. The aircraft began to deviate to the right of the runway centreline around 150 feet before reaching the threshold, and the wheel brakes were applied around 100 feet before the threshold was reached. Around 200 feet after crossing the threshold and at a ground speed of 35 knots, the aircraft's centre of gravity (CG) crossed the right edge of the runway. After the aircraft had travelled about another 20 feet (220 feet beyond the threshold), the TRAs were reduced to approximately forward idle. The aircraft's CG departed the paved surface 270 feet beyond the threshold, and the aircraft came to a stop with its CG approximately 380 feet beyond the threshold.

and the rest of the airplane?

Throttles were, TRA showed...

and laterally?




Figure 3: Ground track analysis. (Source: Boeing)

1.10.2 Cockpit Voice Recorder

The aircraft was equipped with a Honeywell solid-state Cockpit Voice Recorder (CVR). Data from the CVR was successfully downloaded and verified. A transcript of relevant conversations is included in Appendix A to this report.

Who decided what is relevant? The transcript is incomplete.

1.10.3 Spectrum analysis

This is analysis, is not expected here, but in chapter 2

Spectrum analysis of the cockpit area microphone was used to analyse significant sounds, and to determine the exact moment at which the loud bang (that was heard by witnesses) occurred. Following the captain's 'take off' call at 22.36:32 hours (A, Figure 4), the sound of the engines spinning up is visible on the sound spectrum (B). The sound of the engines during the occurrence is visible under line C. At 22.36:36 hours, the captain called 'Set take-off thrust' (D) and the sound of the engines spinning up increases. Around four seconds later a peak can be seen in the sound spectrum, corresponding to the loud bang that was heard (E). The voice of the first officer calling 'abort, abort, abort' is visible at (F), almost immediately followed by the noise of the gear leaving the runway and entering the area of grass (G). (H) is the sound of the TRAs being reduced to idle thrust. The noise made by the deflection of the speed brake handle at around 22.36:55 hours is also visible, at (I).

the nose/ main landing gear?

Is not spectrum. A spectrum shows the level of, and the occurrence of different frequencies. Horizontal scale of a spectrum = frequencies, not time; is frequency domain. What we see here is just sound level (amplitude) during the displayed time.

throttles. TRA indicates throttle angle, the position of the levers. Meant here is noise of throttle levers. You can't hear TRA's.




Figure 4: Spectrum analysis of the occurrence. Each vertical white line corresponds to 1 second.

Legend?

grid

1.11 Wreckage and impact information

After veering off the runway, the aircraft came to a standstill in the field to the right of Runway 21. All of the main gear's wheels had left deep tracks in the soil. A single track made by the nose gear was clearly visible, as were the double tracks left by each main gear. The left nose wheel had left a curved track, which was wider than the tyre itself. Mud had also been thrown up to the right side of the track. The nose wheels were turned slightly to the left.



Figure 5: Photographs of wheel tracks in the soft ground.

The distance from the (displaced) threshold of Runway 21 to the main body gear of TC-ACR was approximately 143 metres. The distance from the entry point of Runway 21 to the aircraft was approximately 363 metres. Skid marks left by the landing gear, deviating to the right, were found on the threshold stripes.

1.12 Tests and research

1.12.1 Engine examination

After the occurrence, engine #4 was transported to the operator's maintenance facility for repair. Investigators observed the engine High Pressure Compressor (HPC) top case tear down that was carried out when repairing the engine. The records show that this tear down did not include the High Pressure Turbine (HPT) section and the burner section, as borescope inspection had revealed that the engine damage was limited to the HPC.

Some engine components were removed during the tear down. These were the HPC stage 3 and 4 blades, two fan blades, two variable stator vane actuators, two variable bleed valve actuators, three temperature sensors, main fuel pump and hydro mechanical control unit. These components were impounded for examination, as they could have contained clues to the cause of the compressor stall. The descriptions and results of the examinations are summarised in Appendix B.

In addition to the engine top case tear down, the Accessory Gear Box (AGB) oil main chip detector was pulled. This showed evidence of minor contamination. Since the FDR oil parameters appeared to be normal, no engine oil filters or chip detectors were pulled for analysis.

1.12.2 Simulator flight

Flight SV916 was reconstructed in a B747-400 full flight simulator. This flight reconstruction (and similar flights using a range of scenarios) was based on FDR data and performance data obtained from flight SV916. Nevertheless, it was not possible to exactly simulate the flight because a reconstruction is an approach to reality and differs with the real circumstances.

of what? PF looks outside, should notice yawing and path deviation. PM should also monitor engine instruments (refer to Boeing procedure in § 1.13.1 below. If the FDR data showed decrease in N1, so did the cockpit instruments.

These simulator flights revealed that:

- When flight SV916 was repeated under the same conditions and circumstances, the aircraft ended up in almost exactly the same place as the actual aircraft did during the incident flight.
- If there are no indications, it takes a crew several seconds to realise that an engine failure has occurred.
- If loss of thrust occurs on engine #4, this causes the aircraft to immediately yaw to the right.
- Noticing and calling an engine failure helps people to react quickly.
- After a yaw to the right, the initial intuitive response is to apply left rudder pedal input in an attempt to keep the aircraft on the runway.
- It takes about one second for a person to move their feet from the bottom of the pedal (rudder) to the upper part of the pedal, to engage the wheel brakes. This could result in a short interval without any pedal input.
- The seat should be adjusted to the right position, as this is essential for maximum wheel braking.
- If the power of the remaining engines is maintained for more than approximately 4 seconds, the aircraft's tendency to yaw to the right cannot be corrected.

When, or during

That is why this is in the procedures.

and pedals

Of course not. The airplane will vacate the narrow runway uncontrolled, by definition, by design, unless the airspeed is equal to or higher than V_{MCG} (or $V1$). Even then, the lateral deviation is up to 30 ft (9,1 m).

- No alert or warning is given when an engine failure occurs during the take-off roll, in conditions similar to the occurrence in question. ?? The alert is the uncommanded yawing.

1.13 Organizational and management information

1.13.1 Certification requirements and Boeing manuals

Is not organizational, but aircraft information (§ 1.6)

The certification requirements relating to the controllability of an aircraft on the ground (V_{MCG}) are set out in the US Federal Aviation Administration Regulations FAR 25.149, effective February 1, 1965. These regulations define V_{MCG} as follows:

V_{MCG} , the minimum control speed on the ground, is the calibrated airspeed during the take-off run at which, when the critical engine is suddenly made inoperative, it is possible to maintain control of the aircraft using the rudder control alone (without the use of nose-wheel steering) as limited by 150 pounds (667 N) of force, and the lateral control to the extent of keeping the wings level to enable the take-off to be safely continued using normal piloting skill. (...)

The remaining of this requirement is interesting too: at V_{MCG} , the path deviates 30 ft (9.1 m)! Below V_{MCG} much more if pilots do not take proper and quick action.

QNH or QNE in Kollsman window?
Write: airport elev 450 ft MSL + the QNH

Did the investigators not verify the crew's calculations?

Given the airport pressure altitude (450 feet) and outside air temperature (5 °C) at the time of the take-off, Boeing calculated that V_{MCG} would have been around 132 knots for a maximum thrust take-off. This number is conservative, as it does not take into account the derated thrust used during this take-off or the effect of nose wheel steering. Also, it assumes that the aircraft is in the critical configuration³ which may not accurately reflect this take-off.

reduced; derating is done by engineers upon installing new more powerful engines on the airplane.

V_{MCG} at lower takeoff thrust levels is lower too.

According to Boeing, to keep control following an engine failure prior to V_1 requires the crew to follow the recommended rejected take-off (RTO) procedure. Boeing does not maintain or publish controllability data for an engine failure below V_1 . Directional control at low speed is accomplished by a combination of nose wheel steering, differential braking, and rudder effectiveness. There is no definitive speed at which the rudder can be called 'effective'; however, the Boeing Flight Crew Training Manual (FCTM) provides the following guidance for initiating take-off roll:

There are none, only "close throttles"

and/or thrust. Heels are on the floor: no diff braking!

Yes, that is V_{MCG} , by definition (FAR 25.149 (e)).

taxi speed, or at low symmetrical thrust. There is no directional control possible at high asym. thrust.

Initiating Take-off roll (747-400)

If cleared for take-off before or while entering the runway, maintain normal taxi speed. When the aircraft is aligned with the runway centre line ensure the nose wheel steering tiller is released and apply take-off thrust by advancing the thrust levers to approximately 1.1 EPR (PW or RR) or 70% N1 (GE). For RR engines, initial EPR settings up to 1.2 are considered acceptable to improve engine operation. Allow the engines to stabilise momentarily then promptly advance the thrust levers to take-off thrust (autothrottle TO/GA). There is no need to stop the aircraft before increasing thrust.

heels on the floor,

³ Maximum available take-off power or thrust on the operating engines; the most unfavourable centre of gravity; the aircraft trimmed for take-off and the most unfavourable weight in the range of take-off weights.

which is aft, because the pressure on the nose landing gear is less, so is its friction on the runway for directional control.

for maintaining the path on the ground only with all engines operative.

of the nose wheels (i.e. not with the tiller)

Keep the aircraft on the centreline with rudder pedal steering and rudder. The rudder becomes effective between 40 and 60 knots. Maximum nose wheel steering effectiveness is available when above taxi speeds by using rudder pedal steering.

But not at max. asym. thrust...

Don't use, can and will be misinterpreted (as in this report). Only if thrust symmetrical.

Regardless of which pilot is making the take-off, the captain should keep one hand on the thrust levers until V_1 in order to respond quickly to a rejected take-off condition. After V_1 , the captain's hand should be removed from the thrust levers. The PM should monitor engine instruments and airspeed indications during the take-off roll and announce any abnormalities. The PM should announce passing 80 knots and the PF should verify that his airspeed indicator is in agreement.

Rejected Take-off (RTO) Maneuver

The RTO maneuver is initiated during the take-off roll to expeditiously stop the airplane on the runway. The PM should closely monitor essential instruments during the take-off roll and immediately announce abnormalities, such as "ENGINE FIRE", "ENGINE FAILURE", or any adverse condition significantly affecting safety of flight. The decision to reject the take-off is the responsibility of the captain, and must be made before V_1 speed. If the captain is the PM, he should initiate the RTO and announce the abnormality simultaneously.

Note. If the decision is made to reject the take-off, the flight crew should accomplish the rejected take-off non-normal maneuver as described in the Maneuvers Chapter of the QRH. (...)

at once. Below V_1 (really below the little lower V_{MCG}) the airplane vacates the runway if asymmetrical thrust is maintained, by definition. This error can be seen as a contributing factor to the accident.

1.13.2 Operators' manuals

Details of the requirements and regulations pertaining to the aircraft in question are set out in the operators' Boeing 747 FCOM. Part B, Appendix II, the Standard Operating Procedures (SOP) and the Quick Reference Handbook (QRH) are included in the FCOM.

Standard Operating Procedures

Details of the take-off procedure are set out in sections 2.29.4 and 2.29.6 of the SOP:⁴

2.29.4 Initiating take-off roll

Auto throttle and flight director use is recommended for all take-offs. However, do not follow F/D commands until after lift-off. A rolling take-off is recommended for setting take-off thrust. It expedites the take-off and reduces the risk of foreign object damage or engine surge/stall due to a tailwind or crosswind. Rolling take-offs are accomplished in two ways.

If cleared for take-off before or while entering the runway, maintain normal taxi speed. When the airplane is aligned with the runway centreline ensure the nose wheel steering tiller is released and apply take-off thrust by advancing the thrust levers to approximately 1.1 EPR (PW) or 70% N1 (GE). (Then) after stabilization, set takeoff thrust.

If holding in position on the runway, ensure the nose wheel steering tiller is released, release brakes, then apply take-off thrust.

⁴ Take-off procedure as described in SOP is consistent with take-off procedure in FCOM 'Normal procedures'.

Why is not the AFM mentioned? This is the formal manual with certified limitations and procedures approved by airworthiness authorities, which FCOM, SOP and QRH are not. These manuals may have been revised by the airline company.

A standing take-off may be accomplished by holding the brakes until the engines are stabilized, ensure the nose wheel steering tiller is released, then release the brakes and promptly advance the thrust levers to take-off thrust (auto throttle TO/GA). Allowing the engines to stabilize provides uniform engine acceleration to take-off thrust and minimizes directional control problems. This is particularly important if crosswinds exist or the runway surface is slippery. The exact initial setting is not as important as setting symmetrical thrust. If thrust is to be set manually, smoothly advance thrust levers toward take-off thrust.

2.29.6 Take-off procedure

is incomplete, and cannot be right. Copied incorrectly?
 In this case, the Captain was PF. Captain under Pilot Flying will not be included in the procedure, so this is not the original takeoff procedure.

Pilot Flying	Pilot Monitoring
<div style="border: 1px solid red; padding: 2px; display: inline-block; margin-bottom: 5px;">PF</div> The Captain will advance thrust levers to approximately 1.1 EPR (PW) or 70% N1 (GE). Allow engines to stabilise.	
The Captain will then push TO/GA switch to advance thrust levers to required thrust, or manually advance thrust levers to the required thrust setting.	
<div style="border: 1px solid red; padding: 2px; display: inline-block; margin-bottom: 5px;">?? Is done already. Check?</div> Call "SET Take-off THRUST"	
Verify that the correct take-off thrust is set.	<div style="background-color: #FFFF00; padding: 2px;">Monitor the engine instruments throughout take-off. Call out any abnormal indications.</div> Adjust take-off thrust before 80 knots as needed. During strong headwinds, if the thrust levers do not advance to the planned take-off thrusts, manually advance the thrust levers before 80 knots. Call "THRUST SET"
<div style="border: 1px solid red; padding: 2px; display: inline-block; margin-bottom: 5px;">Or PF?</div> Captain's hand must be on the THR Levers until V ₁ .	
Monitor airspeed. Maintain light forward pressure on the control column	Monitor airspeed indications and call out any abnormalities.
Verify 80 knots and call, "CHECKED"	Call "80 KNOTS."
(...)	(...)

Should this not be the Pilot Flying? What QRH says is that after engine failure first a discussion about fault analysis is required, then the captain has to decide. Takes time, is not expeditiously. Error in QRH!

Quick Reference Handbook

QRH, Section 1 Non-normal manoeuvres section, provides the following guidance for initiating a rejected take-off:

Rejected Take-off

The captain has the sole responsibility for the decision to reject the take-off. The decision must be made in time to start the rejected take-off manoeuvre by V_1 . If the decision is to reject the take-off, the captain must clearly announce "REJECT," immediately start the rejected take-off manoeuvre, and assume control of the airplane. If the first officer is making the take-off, the first officer must maintain control of the airplane until the captain makes a positive input to the controls.

This is a bad line. Below V_1 (really V_{MCG}), failure of #1 or #4 will result in vacating the runway, for sure. RTO below V_1 must be initiated asap, not by V_1 .

not to V_1 ?? or any time before reaching V_1 ? What between 80 kt and V_1 ?

Prior to 80 knots, the take-off should be rejected for any of the following.

- activation of the master caution system
- system failure
- unusual noise or vibration
- tire failure
- abnormally slow acceleration
- take-off configuration warning
- fire or fire warning
- engine failure
- predictive wind shear warning (as installed)
- if the airplane is unsafe or unable to fly
- (...)

By then, the airplane already will have vacated the runway, if an outboard engine fails.

This procedure cannot be right. Did Boeing write this, or the operator?

During take-off, the crew member observing the non-normal situation will immediately call it out as clearly as possible.

Where is this procedure from? Why included? Is for high speed abort.

Captain PF?	First Officer PM?
Without delay.	Verify actions as follows.
Simultaneously close thrust levers, disconnect auto throttle, and apply maximum manual wheel brakes or verify operation of RTO autobrake.	Thrust levers closed.
If RTO autobrake selected, monitor system performance and apply manual wheel brakes if AUTOBRAKES message displayed or deceleration not adequate.	Auto throttle disconnected.
Raise speed brake lever. Useless at low speed.	Maximum brakes applied.
Apply the maximum amount of reverse thrust on symmetric engines consistent with conditions.	Verify speed brake lever UP and call "SPEEDBRAKES UP." If speed brake lever not UP, call "SPEEDBRAKES NOT UP."
Continue maximum braking until certain the airplane will stop on the runway.	Reverse thrust applied symmetrically. When all REV indications are green, call "REVERSERS NORMAL."
Field length permitting. Initiate movement of reverse thrust levers to reach reverse idle detent by taxi speed.	If there is no REV indication(s) or the indication(s) stays amber, call "NO REVERSERS ENGINE(S) NUMBER ___" or "NO REVERSERS".
(...)	Call out any omitted action items. Call out 60 knots.
Only approved when the airspeed is above 60 kt. When during landing the airplane decelerates below 60 kt the throttles should already have been moved to reverse idle detent. That is why 60 kt is to be called. In this case, during takeoff at an airspeed <42 kt, the use of reverse thrust was not at all authorized.	Communicate reject decision to control tower and cabin as soon as practical.
	(...)

1.13.3 Training

Simulator training

The flight crew performed the regular mandatory training and check flights, as put down in Operation Manual Part D (training manual) in a full flight simulator. The flights in question are the Operator Proficiency Check (OPC), License Proficiency Training (LPT) and the License Proficiency Check (LPC). OPCs are flown every six months, while LPTs and LPCs are flown once a year. Details of each of the topics to be taught or checked are laid down in the assessment forms. These must all be covered within a three-year period. Prior to each simulator session, the flight crews are briefed on which items will be taught or checked in that particular session, to give the crews the opportunity to prepare themselves for the flight. Two trainees are trained and checked per simulator session. The topics involved are divided between trainee1 (TR1) and trainee 2 (TR2). The items to be taught and checked with regard to RTOs are set out in the forms, as depicted below.

	Year 1	Year 2	Year 3
OPC	TR1. Low speed RTO Rejected T/O in low visibility TR2. RTO (contaminated runway)	TR1. High/low speed RTO (contaminated runway) Rejected T/O in low visibility TR2. RTO	TR1. High/low speed RTO Rejected T/O in low visibility TR2. RTO (wet runway)
LPT	TR1. Low speed RTO Engine fail/ before V ₁ / RTO TR2. Take off RTO (pilot incapacitation)	TR1. Low speed RTO TR2. RTO before V ₁	TR1. Low/High speed RTO (wet runway) TR2. RTO (contaminated runway)
LPC	TR1. High/low speed RTO (contaminated runway) Briefing, rejected Take off, engine failure in low visibility TR2. RTO	TR1. High/low speed RTO Rejected T/O in low visibility, engine failure TR2. RTO	TR1. High/low speed RTO (contaminated runway) Rejected T/O in low visibility, engine failure TR2. RTO

Table x. ...

CRM Training

The flight crew had taken the annual, mandatory Crew Resource Management (CRM) training course. One of the topics covered in 'year two' of this training course, is the "Surprise and Startle" effect. Here, the causes and consequences of this phenomenon are discussed. Various case studies are presented, and recommendations are made on how to prevent this effect.

You don't answer the probable question whether the crew indeed received this training.

1.14 Additional information

1.14.1 Measures taken by the operator

Belongs in § 4 (safety actions already implemented).

After the occurrence in question, the operator initiated two risk assessments by external parties. One assessment dealt with the runway excursion, while the other focused on the engine failure. The results were presented in an internal report.⁵

Regarding the runway excursion, the following mitigating actions were performed or planned:

- One extra simulator session has been performed to examine the effectiveness of the RTO procedures at low speed.
- A Flight Crew Assessment Board meeting has been held for related crew assessment.
- RTO procedures were reviewed
- The number of low speed RTO practices in yearly training program will be reviewed depending on simulator RTO examine session with coordination of training department. After this review the training program was extended with an Operator

⁵ Operators action-taken report concerning the TC-ACR runway excursion.

Proficiency Training (OPT). Four RTO procedures are trained during this three-year program, divided between Trainee 1 and Trainee 2.

- A safety notice was published to all flight crew to remind RTO procedures.
- Internal safety investigation was carried out by SMS department.

The flight assessment committee planned and carried out an extra simulator session to check current RTO procedures under low speed conditions, and to assess the flight crew involved. This produced the following findings:

- The time to start RTO especially at wet/contaminated runway is very important.
- Flight crews should start the RTO procedure without hesitation when recognizing that the airplane is significantly deviating from the runway centre line.

the moment, the instant

? What is significant? Then too late. ... deviating uncontrollable...

Regarding the engine failure, the following mitigating actions were taken:

- Engine core wash.
- Engine high pressure compressor (HPC) borescope inspections.
- Other possible mitigation measures will be implemented in accordance with GE's recommendation.

1.14.2 Information about engine #4

Belongs in § 1.6.

The operator purchased aircraft TC-ACR from another European operator in June 2015. An inspection prior to the delivery flight revealed some damage to parts of the HPC (stage three blades) in the incident engine (#4). After consultation with the engine manufacturer, it was concluded that the damage was within Aircraft Maintenance Manual (AMM) limits, and that there was no objection to the operation of the aircraft.

So, was the AMM correct? Were there no operating hours/ engine cycles limitations issued?

All pertinent information necessary for the reader to understand the analysis should be included, and easily and quickly to be found in the standard location (§ number). Maintain this numbering, even if a § remains empty. People who often read reports, know the § numbers and titles.

Too much information in this report is spread out in paragraphs, making it difficult to find for readers.

Detailed guidance on completing each section is presented in ICAO Doc 9756 Part IV - Reporting.

DTSB should also review ICAO Doc 9756 Part IV - Reporting Appendix 2 to Chapter 1 - Report Writing Conventions.

2 INVESTIGATION AND ANALYSIS

2.1 General

Which one? The FAA Approved Weight and Balance Control and Loading Manual, referenced in the TCDS?

You should mention what is stated in § 1.14.2 above.

Aircraft TC-ACR was properly certificated and equipped, in accordance with the requirements. According to the flight and technical logs, no defects or anomalies were encountered during the previous flight. There were no indications that the aircraft had any defects before the start of flight SVA916 to Jeddah. Nor was there any evidence of an existing power plant failure or systems failure before the flight commenced.

The aircraft was loaded in accordance with the loading instruction report. The aircraft's weight and balance were all within limits. Its centre of gravity was almost in the centre of the flight envelope. For this reason, it was concluded that weight and balance played no part in causing this occurrence.

cg envelope. Flight envelope is something else. You should have shown the cg/weight envelope.

The flight crew consisted of the captain and the first officer. The captain acted as pilot flying and the first officer as pilot monitoring. Both were properly certified, qualified and trained to perform these roles during the flight. Given the number of flight hours and the amount of experience they had accumulated, they can both be deemed to be experienced with the type of aircraft in question, a Boeing 747. This was their first flight after two days leave. Both members of the flight crew stated that they were well rested. Two additional crew members, a technician and a load master had no active role during the flight.

considered

Although Maastricht Aachen Airport normally closes at 22.00 hours, an exemption was granted to allow the aircraft to take-off no later than 23.00 hours. This was because loading operations had not been finished in time. Around 22.19 hours, the crew and the aircraft were ready for departure and the push back onto the taxiway was performed. Although the captain stated in his interview that he felt a little hurried, CVR data indicated that the flight crew had acted calmly prior to the incident.

The incident occurred at night, with overcast skies that blocked any moonlight. This caused one member of the crew to remark about the darkness. All taxiway and runway lights were lit in accordance with the requirements. Given the atmospheric conditions, the setting of the lighting was appropriate. The runway was damp but not slippery. There are no indications that the weather, atmospheric conditions or runway conditions were involved in causing the occurrence.

had influence

2.2 The flight and the occurrence

Flight preparations and the start of flight SVA916 were all routine. Both pilots performed their tasks as set out in the operator's SOPs. The start-up, the before taxi checklist and the before take-off checklist were all completed before taxi commenced. In view of the distance between the stand and the runway, this was understandable. In fact, this enabled the pilots to concentrate fully on the task of taxiing to the runway in darkness.

The crew received take-off clearance while approaching Runway 21. This enabled them to commence a rolling take-off, maintaining a ground speed of approximately 5 kts during the right turn to line up on the runway. At 22.36:34 hours, the captain advanced the thrust levers to approximately 70%. As thrust increased to the selected take-off power, a minor difference developed between engine #4 and the remaining engines. As a result, some pedal steering inputs were required to keep the aircraft aligned with the runway centreline. At this time, engine #4 (and, to a lesser extent, engine #3) was producing noticeably more thrust than the other engines. The steering inputs were to the right, as the difference in thrust was causing the aircraft to veer to the left.

#1 (FDR data)

Not shown in figure on page 17.

?? FDR data #1!

Why not all FDR data included? You should have done that for readers to be able to verify (Annex 13 App 1-1).

When the engines had stabilised at 70% N1 the captain pressed the TO/GA switches, thus engaging the autothrottle. The captain's call-outs and actions, and those of the first officer, were all in accordance with the SOPs. However, the first officer's saying 'Set thrust', followed by the captain's 'Take off' are not mentioned in SOPs or checklists. No explanation could be given for these calls. The whole sequence of the crew's actions was in keeping with a routine flight, involving nothing out of the ordinary.

??

CRM was not good!

ground speed? Where from?

During the start of the take-off roll, the tasks were divided up as prescribed in the manuals; the captain was looking outside and keeping the aircraft in the middle of the runway, while the first officer monitored the instruments. Four seconds after the autothrottle was engaged, at a ground speed of 30 kts, a loud bang was heard and the N1 of engine #4 dropped to around 20%. In his interview, the captain stated that he did not hear the bang because he was the only one who was wearing an active noise cancelling headset over both ears and because the noise originated from the right side of the aircraft. The first officer had only one of his ears covered by his headset, while neither the technician nor the load master were wearing headsets. The fact that only these three individuals heard the bang confirms the assumption that the captain did not hear the noise because it was muted by his headset.

attenuated

Unable to hear the loud bang, the captain could not understand why the aircraft was suddenly yawing to the right-hand side of the runway. This triggered the normal response of trying to counteract this yaw by steering to the left, by means of nose wheel rudder pedal steering. As the captain was still applying the right rudder pedal, it took some time before he could switch to the left rudder pedal once the right yawing occurred. The captain also stated that he used the nose wheel steering tiller to steer the aircraft to the left.

2.2.1 Application of the tiller

The tiller is **designed** to steer the aircraft on the ground, by turning the nose wheel. The tiller can be used to turn the nose wheel up to 70 degrees left and right, **when** making tight turns. The use of differential thrust is limited to very tight turns, for instance when an aircraft has to make a 180-degree turn on the runway. In all other situations, the tiller and – to a lesser extent – differential braking is used. If high turning angles are used, taxi speed should be limited to around 10 kts, to avoid nose wheel skidding.

during taxiing

At V_{MCG} , the horizontal displacement away from the runway centerline when an outboard engine fails, is still 30 ft (10m) (FAR 25.149)

By design, the tiller and the rudder pedals both use the same actuators on the nose wheel. The tiller inputs override control inputs by the rudder pedals. Steering input from the rudder pedals is limited. They are unable to turn the nose wheel by more than 7 degrees. This prevents nose wheel skidding during the take-off roll, when maximum input is being applied to the rudder pedals. As the rudder control surface is controlled by the rudder pedals, maximum control input is necessary when operating the aircraft just above V_{MCG} in case an outboard engine failure should occur.

Bad sentence. The rudder is, by design, only large enough to counteract asym thrust at airspeeds above V_{MCG} (V_1).

According to the manuals, use of the tiller during a take-off roll should be avoided. The tiller should, therefore, be released by the pilot. If the nose wheel is turned more than 7 degrees, this increases the risk of nose wheel skidding, which makes steering less effective. Therefore, the rudder pedals should be used to steer the aircraft down the centreline of the runway. At the start of the take-off roll, the captain should normally have one hand on the control column and the other on the throttles. The FCTM of Boeing and the SOPs of the operator direct the captain to keep hold of the throttles at all times until V_1 is reached, after which point a safe reject manoeuvre can no longer be guaranteed.

Do manuals indeed state this?

?? → After V_1 , both hands are normally positioned on the control column.

it cannot be guaranteed that the airplane can come to a full stop on the remaining runway

2.2.2 Flight control inputs during the incident

Following push-back and engine start, both the before taxi checklist and the before take-off checklist were completed before the aircraft taxied to the runway. During taxiing, the captain had to perform two 90-degree turns to align the aircraft with the runway centreline. As he taxied the aircraft, he used his left hand to operate the tiller while using his right hand to increase the thrust slightly to achieve a taxi speed of around 5 kts (consistent with the FCTM's recommended taxi speed for 90 degree turns).

This is standard, why mentioned?

FDR stick force data? Show these data.

As he aligned the aircraft with the runway centreline, the captain increased thrust to perform a rolling take-off. Thrust is set using the right hand, so the captain's right hand was holding the thrust levers. At that time, he was operating the tiller with his left hand. This suggests that he was not holding the control column. This was confirmed by FDR data, which showed that zero force was being exerted on the captain's control column at that point. The thrust difference between the engines during spin-up was such that the N1 of engine #4 was higher than the N1 of the other three engines. This resulted in a yaw to the left. As a result, the captain had to make corrections with the rudder pedals, steering to the right during the initial phase of the take-off.

Where are these data?

Why take off thrust level not listed?

Where is yaw data?

No, FDR data shows N1 #1 little higher initially (Figure 2 page 16).

Where are these data?

The captain then felt the aircraft yaw suddenly to the right. Unaware of the cause, he tried to arrest this movement by using nose wheel steering inputs. As stated, he used both pedal and tiller nose wheel steering. However, tiller inputs override rudder pedal inputs.

He doesn't have to know the cause at this point, but should react to the uncommanded yawing, by closing the throttles (being below V_1).

His statement? What does FDR heading data show? Figure 3 on page 17 shows very slow yawing, not at all a sudden yaw.

Effect of crosswind? No rudder required to counteract the weathercock tendency?

When it became clear that nose wheel steering was not sufficient, he applied brake pressure. This occurred three seconds after the beginning of the event, as shown by an increase in the main gear brake torques. FDR data showed that, initially, both the right-hand and left-hand main gear brakes were engaged. Shortly thereafter, braking of the right-hand gear decreased, which is indicative of differential braking. Although the aircraft had initially been heading a little to the left, it subsequently experienced an increasing deviation to the right. As take-off power was still engaged, the combined effect of tiller nose wheel steering and differential braking was insufficient to counteract the yaw to the right.

Where are these data?

Where are these data?

According to FDR data a control wheel input (steering to the left) was recorded shortly after the engine failure occurred. Thus, while the captain was holding the tiller with his left hand, he had most probably moved his right hand from the thrust levers to the control wheel. The captain was of the opinion that he had retarded the thrust levers almost immediately after noticing the deviation. However both FDR data and CVR data showed that the thrust levers were retarded to idle approximately eight seconds after the N1 drop of engine #4. This means that asymmetric thrust was acting on the aircraft for eight seconds.

The captain stated that he had tried to steer the aircraft to the left, using the tiller to keep the aircraft on the runway, while the first officer stated that he did not operate any controls. Thus, it was concluded that the captain's left hand remained on the tiller until the aircraft had come to a full stop at its final resting place. Tiller inputs are not recorded on the FDR, so additional data was analysed for evidence of the use of tiller nose wheel steering. This analysis is based on three strands of evidence.

1. Tyre marks in the soft ground

The tyre marks associated with each individual landing gear strut were carefully examined. The nose wheel tracks in the grass were of particular interest. It was concluded that the shape and size of the nose wheel track in the grass indicated a nose wheel steering angle ranging from around 26 degrees to around 36 degrees to the left. This track ran from the point where the nose wheel had left the runway surface to the aircraft's final resting place. Although the calculated steering angles (based on the nose wheel track) are merely an indication, they clearly exceed the maximum steering angle of 7 degrees that can be achieved by pedal steering. It is, therefore, very likely that this was caused by inputs to the tiller nose wheel steering system.

Couldn't this be caused by the drag of the mud also? Kind of skidding?



Figure 6: Analysis of the nose wheel track. The red line indicates the orientation of the aircraft; the yellow line indicates the angle of the nose wheel.

2. Damage to the aircraft

Boeing's analyses of the forces exerted on the nose wheel, which were responsible for the damage to the front section of the aircraft, revealed that the deceleration force on the nose wheel was consistent with a nose wheel steering angle of more than 7 degrees. According to the manufacturer, all ground loads act on the well structure (~~doghouse~~) of the nose landing gear. Although the actual loading involved in this case was difficult to quantify, based on the buckle pattern in the skin (45-degree pattern in the buckles), it appears that there was a significant amount of compression-shear-related loading. This is consistent with a left turn, due to the operation of the tiller, which would force the doghouse loads into the supporting structure (including the skins), as compression.

nose landing gear wheel well

Is this measured and recorded? Or assumed?

to distribute/transfer

there was no left turn, was there (Fig. 6)? Tiller to the left?

3. FDR

FDR analysis revealed that left control wheel input was recorded from the moment the engine failure occurred until the moment the throttles were finally retarded to idle. There was an interval of 1 second between control column release and retardation of the throttles. This is consistent with the time required for the captain to move his right hand from the control column to the throttles. Accordingly, it is likely that the captain was not holding the control column with his left hand, but that he was instead using this hand to operate the tiller. It can be concluded that the captain was holding and using the tiller throughout the event, making control steering inputs that exceeded 7 degrees of nose wheel steering. ??

No recording of earlier inputs?
Where are the data for the readers to confirm? Ah, some in Figure 7 below, why not refer to this Figure here?

No, FDR data doesn't show this, see Figure 7 below.

Capt was PF and had to hold on to the throttles until reaching V1!




Figure 7: Plot of FDR data (TRA, control column, control wheel, rudder pedal). The red vertical line indicates the point at which the N1 of engine #4 dropped; the black vertical line indicates the moment at which the throttles were retarded.

Reject and abort used, are not the same.

Not first the bang, then the yawing? Where are the FDR heading data?

Is black on page 16.

How do you know?

2.2.3 Rejected take-off procedure (RTO)

During the take-off procedure, the first officer's task is to monitor the engine instruments, call out any abnormal indications, and adjust take-off thrust as necessary until the aircraft reaches a speed of 80 kts. Initially, all engine instrument readings were normal. Thus his attention was focused on the air speed indicator, as he was required to call out the speed when the aircraft reached 80 kts. Immediately after the aircraft yawed to the right, the first evidence that an anomaly had occurred was the loud bang that he heard. No caution or warning was audible or visible on the EICAS, but the combination of the bang and the yaw indicated to him that the situation was very serious. That was probably why – almost immediately after these events – he called “off, abort, abort, abort”, in an effort to get the captain to abort the take-off. The interval between the bang and his abort call was a little more than one second. Partly because there was no caution or warning, he did not notice the drop in engine #4's N1. As a consequence, he did not call out 'engine failure' as a reason for rejecting the take-off (the procedure specified in the manuals). Because the first officer did not announce the reason for the RTO, the captain did not know what had prompted the first officer's abort call.

He obviously was not monitoring engine rpm

abort

Was this a correct call? No, should have included "#4 failure"

Despite the call to abort the take-off, the captain initially tried to keep the aircraft on the runway by a combination of steering and braking. The thrust levers were retarded to forward idle about eight seconds after the N1 of engine #4 dropped, and around six seconds after the first officer's call to abort. The selection of reverse thrust resulted in

You're telling a story, looking for excuses, should report facts. This is not a novel, but an investigation report. Write facts, not fiction.

Selecting reverse thrust at this low speed is not approved.

automatic disconnection of the autothrottle and extension of the speed brakes. At that point, the aircraft had already veered off the runway to the right and had rolled onto the grass. The thrust levers were not closed immediately, so they were still at the take-off power setting when the aircraft veered off the runway and rolled onto the soft ground. By the time the thrust levers were moved to ~~forward~~ idle, the speed of the aircraft had already dropped almost to zero, due to the combined effects of the applied brakes and of the drag created by the soft ground.

Information obtained from the FDR, the CVR and the pilot interviews showed that the standard rejected take-off procedure had not been followed. Although the first officer was aware of the need to reject the take-off, the captain's actions were consistent with an attempt to keep the aircraft on the runway by means of rudder pedal, braking, control column and tiller inputs. It can be concluded that, during the event, the captain had been using his left hand to operate the tiller and that he had moved his right hand from the throttles to the control wheel. This means that the captain was no longer holding the throttles, in contravention of the take-off procedure. as is operating the tiller.

a ??

As the throttles were not retarded, a runway excursion became inevitable. This is because, if there is an outboard engine failure at ~~low speed~~, while the remaining engines are at ~~take off thrust~~, it is impossible to keep the aircraft on the runway. at speeds below V_{MCG} .

max. thrust (V_{MCG} is measured at the max. thrust that a pilot can set in the cockpit - is worst case)

2.3 Asymmetric thrust

The drop in engine #4's N1 resulted in an asymmetric thrust. Engines #1 and #2 on the left side of the aircraft were producing more thrust than engines #3 and #4 on the right side, which resulted in a yaw to the right. The effect of a loss of thrust on engine #4 seizing was amplified by the fact that this engine is on the outside of the wing, which resulted in the loss of a large moment on the right side. The outside engines (#1 and #4) are defined as critical engines: "the engine whose failure would most adversely affect the performance or handling qualities of an airplane."⁶

distribution on the airplane

No need to mention #2 and #3.

failing #4

thrust yawing

outboard

ground speed? Rudder power from airspeed! Where this data from?

The purpose of the RTO procedure described in the manuals is to keep an aircraft under control after an engine failure prior to V_1 . Directional control at low speed is accomplished by a combination of nose wheel steering, differential braking and rudder effectiveness. The rudder only becomes effective at speeds of between 40 and 60 kts. Thus, it was not effective in this case, as the aircraft's ground speed was around 30 kts when the N1 of engine #4 dropped. This incident has shown that, when three engines are producing take-off power and an outboard engine loses power, nose wheel steering and differential braking are not sufficient to keep the aircraft in the middle of the runway. To counteract the effects of asymmetric thrust at low speed, immediate action is required. As stated in the manuals, a crew member who observes an anomalous situation of this kind must immediately call this out as clearly as possible, stating the nature of the anomaly. According to the manuals the appropriate procedure for neutralizing asymmetric thrust is

Only #1 caused the airplane to deviate from the runway centerline after failure of #4. #2 and #3 produced symmetrical thrust. Nose wheel steering is never adequate for keeping the airplane on the centerline at airspeeds below V_1 . That is why a takeoff with a multi-engine airplane always has to be aborted at airspeeds below V_1 when an engine fails.

No, to expeditiously stop the airplane (see page 21). Below V_1 , the airplane cannot be controlled.

Not to counteract, is impossible. Close throttles.

when thrust is symmetrical. When asym thrust, only effective at airspeeds above 132 kt this case. It is of no use to mention effectiveness 40-60 kt here.

The writer of this paragraph has not understood certification requirements and V_{MCG} . An airplane only has to be controllable on the ground after engine failure at airspeeds higher than V_{MCG} (is a minimum speed). For this reason V_{MCG} has to be determined and is used in the calculation of V_1 . Below that speed, an engine failure must lead to aborting the takeoff at once. An airplane can never be controllable at speeds below V_{MCG} when takeoff thrust is set.

to simultaneously close the thrust levers, disconnect the autothrottle, raise the speed brake lever, apply maximum wheel brakes and apply maximum reverse thrust on symmetric engines.

?? Not approved below 60 kt!

As shown during test flights in the full flight simulator, unless appropriate action is taken within about four seconds, it is impossible to keep the aircraft on the runway after an outboard engine failure under the same (derated) conditions. In the case of a full rated take-off, the available response time would be even shorter.

Of course. That is why procedures exist!

Certification requirements regarding the controllability of an aircraft on the ground when a critical engine becomes inoperative, V_{MCG} , ~~only apply to speeds at which it is possible to maintain control of the aircraft using the rudder control alone.~~ In the case of TC-ACR, this speed would have been around 132 kts. This highlights the fact that there are no certification requirements for cases in which a critical engine becomes inoperative at low speed.

Refer to remarks on page 20. During flight testing, the critical engine is off, but V_{MCG} applies after failure of either engine.

the exact number must have been known to the pilots and investigators.

2.4 Engine failure

It was the failure of the captain by not responding adequately to yawing at low speed that led to this accident. Is a conclusion - write this later.

~~It was the loss of thrust on engine #4 that led to this incident.~~ The cause of the loss of thrust was not investigated in depth, as contained single engine failures do not automatically meet the criteria for an accident or serious incident. However, the engine was subsequently disassembled for repair by means of a top case tear down, which presented the opportunity to examine some components.

?

Where are these data?

High Exhaust Gas Temperature (EGT), a low stabilised core engine speed of around 79% and falling, plus the drop in engine #4's N1 (fan speed) following a loud bang, are all strong evidence of a compressor stall.

which?

The laboratory analysis found no animal cell material or DNA of animal origin. Based on this finding and on the absence of other foreign material, it can be concluded that the compressor stall was not caused by Foreign Object Damage (bird, litter).

Compressor stalls can sometimes occur in strong and gusty crosswind conditions. However, taking into account the prevailing wind conditions at EHBK (250/03, varying from 210 to 330) during take-off, the weather can be ruled out as a causative factor of a compressor stall.

In the high-pressure compressor (HPC), there was evidence of damage to some of the compressor blades in stages 3 and 4. A metallurgical investigation demonstrated that this damage had existed prior to the event. It seems that the damage to some stage three blades in the HPC had previously been assessed by the engine manufacturer, who had concluded that this damage was within acceptable limits. Hence, there was no objection to the operation of the aircraft with this engine (General Electric, CF6-80 series, s/n 706-509) installed at position #4. Therefore, as the HPC damage was considered to be minor, this cannot solely account for the compressor stall. After all, the engine was operated several flight without any problems.

?? Almost every mishap airplane operated several flights without problems...

Many parts of engine #4 that are related to the engine control loop showed anomalies, with respect to their condition or performance. No fault messages were shown in earlier flights, however the absence of messages does not exclude these anomalies. The Dutch Safety Board took the decision to refrain from any further analysis of the compressor stall and has no opinion on maintenance because this has not been investigated. Nevertheless, the technical state of the engine may well have been a factor here, given the overall condition of the components related to the engine control loop and the condition of the fuel pump.

Why mention this? Now I want to know more about the technical state of the engine. This is an investigation report.

2.5 Noise cancelling headsets

The captain, as the only member of the crew, had covered both ears with a noise cancelling headset. The American FAA drew attention to the use of these types of headsets twice. In Info Bulletin 07001 of 5 January 2007 and in Special Airworthiness Information bulletin CE-16-08 of 20 November 2015 the FAA advises operators and pilots of concerns with the use of noise cancelling headsets. When wearing these headsets, the pilot may be unaware of environmental sounds and audible warning annunciations in the cockpit that do not come through the intercom system. Noise cancelling headsets are most effective over a narrow frequency range, but the specific frequencies may vary by make and model. Therefore, it is difficult to assess any effects the headsets may have on discerning environmental sounds such as:

but always the lower frequencies (< 500 Hz)

- Vital communications between flight crew members or flight attendants, other than those attainable through interphone operations;
- Abnormal mechanical noises or abnormal engine sounds;
- Audible alarms other than those discernible by electronic means;
- Vibrations or wind noises;
- Other aircraft during ground operations.

A good spectrum of the bang and other sounds might have helped in this analysis.

Therefore operators and crew members of aircraft are advised to evaluate their use of noise cancelling headsets.

2.6 The startle effect

Following the loss of thrust on engine #4, the crew did not respond as they had been trained to and their actions were not in accordance with the RTO procedures described in the manuals. This behaviour could be explained by a phenomenon known as a 'startle effect'. In aviation, a startle effect can be defined as an uncontrollable, automatic reflex that is elicited by exposure to a sudden, intense event that violates a pilot's expectations.⁷

'Startle' is highly unlikely. The event was not sudden, not intense, was not an upset. The takeoff run just started. The captain was not paying attention. Was the occurrence of an engine failure during takeoff not discussed during the takeoff briefing (CVR)? Was this crew engaged to perform well (CVR)? Seems they didn't really care, given the few lines of the CVR transcript that were included in this report.

⁷ FAA Advisory Circular 120-111 dated 4/14/15 - Upset Prevention and Recovery Training.

The startle effect has been described extensively in the Skybrary article about this subject.⁸ According to this article: *"The startle effect includes both the physical and mental responses to a sudden unexpected stimulus. While the physical responses are automatic and virtually instantaneous, the mental responses - the conscious processing and evaluation of the sensory information - can be much slower. In fact, the ability to process the sensory information - to evaluate the situation and take appropriate action - can be seriously impaired or even overwhelmed by the intense physiological responses.*

In addition to the temporary physiological changes which follow a high intensity stimulus, studies have determined that, following a startling stimulus such as a loud noise, basic motor response performance can be disrupted for as much as 3 seconds and performance of more complex motor tasks may be impacted for up to 10 seconds.

The time that it takes to recover in a cognitive sense, after a startle event, must also be considered. Startle has been found to impair information processing performance on mundane tasks, such as the continuous solving of basic arithmetic problems, for 30 to 60 seconds after the event occurrence. The duration of the performance degradation increases as the task becomes more complex. Thus, the startle effect disrupts cognitive processing and can negatively influence an individual's decision making and problem-solving abilities.

*As concluded by Martin, Murray and Bates in their paper *The Effects of Startle on Pilots During Critical Events*,⁹ the reliability of modern aircraft is part of the context in which inappropriate actions are sometimes taken after an unexpected event:*

"... one of the common themes as aircraft become more reliable is that pilots are surprised or startled by some event and as a result have either taken no action or alternatively taken the wrong action, which has created an undesired aircraft state, or in some cases, an accident. This surprise or startle is largely due to the enduring reliability of the aircraft and the aviation system, which has unwittingly created a conditioned expectation of normalcy among today's pilots. The problem then is the level of expectation of novel or critical events is so low that the level of surprise or startle which pilots encounter during such events is higher than they would perhaps have had some decades ago when things went routinely wrong."

On the flight deck, pilots may be exposed to a variety of stimuli that have the potential to elicit the startle reflex and response. Bird strike, aircraft upset, simultaneous failure of multiple engines and visual stimuli, such as sudden illumination by lasers, have all resulted in incidents where pilots have been startled or even disoriented. In aviation, the immediate impact of the startle reflex may induce a brief period of disorientation as well as short term psychomotor impairment which may well lead to task interruptions and/or a brief period of confusion. Should this happen, a period of time will be required for reorientation and task resumption. While performance after a startle event can be

⁸ https://www.skybrary.aero/index.php/Startle_Effect.

⁹ Martin, W., Murray, P. and Bates, P. (2012). *The Effects of Startle on Pilots During Critical Events: A Case Study Analysis*. www98.griffith.edu.au.

affected to the detriment of safety of flight, the greater concern stems from what the crew did, or did not do, during the conditioned startle response itself. It is here that decision making can be most significantly impaired, especially higher-order functions necessary for making judgments about complex flight tasks."

This investigation revealed that the flight crew's actions corresponded to some symptoms of the startle effect, as described above. In the interval until the aircraft had come to a complete stop, no mention was made of engine failure and the captain's RTO actions were not monitored, nor was there any communication between the members of the flight crew. Such actions are consistent with the impact of a startle event. Someone asked 'what happened?' after the aircraft had stopped, indicating that their actions were prompted by surprise.

People experiencing a sudden, intense event can show target fixation. They may also experience communication difficulties and be unable to follow standard procedures. This was the case here. The captain's actions were focused on keeping the aircraft on the runway, the target he was fixating on. With regard to the thrust levers in particular, the procedures he had been taught (which are also described in the manuals) seemed to have been forced into the background. This lasted until the aircraft had come to a complete stop in soft soil. The first officer became aware that an anomaly had occurred when he heard the loud bang, which was immediately followed by the aircraft yawing to the right. His initial reaction to these events was to call out 'Off, abort, abort, abort', although he did not immediately state his reasons for doing so. In addition, the standard RTO procedures were not followed. This is consistent with the 'startle effect'.

The flight crew (like all of this operator's flight crews) underwent flying training and check flights three times a year. Within a period of three years, all of the topics listed on the assessment form have to be taught and checked. Each session includes one type of RTO, e.g. standard RTO, plus high speed and low speed RTOs on contaminated runways. Each year, they are trained in low speed RTOs following an engine failure. Before each simulator session, the flight crews are briefed on the items to be taught or checked in that particular session. This is to give them the opportunity to prepare themselves for the flight. As a result, the crew members are not surprised when an engine failure occurs at low speed during take-off in that simulator session. Knowing what to expect, they are well prepared for the actions that need to be taken. Any startle effects encountered in this setting will be very limited, compared to those that crews experience when exposed to 'real life' events.

The crew was well rested, just commenced the takeoff. Every multi-engine airplane pilot knows what to do when the airplane deviates from the runway centerline early in the takeoff roll and what the only cause can be, and the only response should be: abort by closing all throttles. The training obviously fell short, not only in airplane handling, but also in cockpit communication, in CRM. Has nothing to do with startle effect. Using startle effect is looking for inappropriate excuses. Fortunately, nobody got hurt.

Did you verify with checklist, QRH, SOP? Was the takeoff checklist really completed as presented in the VCR transcript?

3 FINDINGS AND CONCLUSION

3.1 Findings

The aircraft TC-ACR was properly certified, equipped and maintained, in accordance with requirements. There was no evidence of an existing power plant or systems failure prior to the commencement of the flight.

Where discussed in this report?

The aircraft's weight and balance were within limits.

These were not presented in this report, should have.

The take-off performance calculations were in accordance with the procedures.

The captain and the first officer were properly certified and qualified for the roles they were to perform during the flight.

There is no evidence that the weather, atmospheric conditions or runway conditions contributed to this occurrence.

When take-off power was selected, a compressor stall occurred in engine #4. At this point the aircraft had a ground speed of around 30 kts and had not yet reached maximum take-off power.

being

?? Not airspeed?

the engines? Was max. set?

The compressor stall resulted in loss of thrust of engine #4 (N1 decreased to 20%) after which the thrust distribution was asymmetrical.

The loss of thrust resulted in engine #4's N1 dropping to around 20%, thereby producing asymmetric thrust.

#4 did not produce asymmetrical thrust, #1 did.

The pilot monitoring did not notice the loss of thrust on engine #4, but he was aware of the seriousness of the situation and urged the captain to abort the take-off.

did not communicate correctly.

He must have been aware, because of all control inputs. The captain should not wait for PM calls!

Because the pilot monitoring did not announce the loss of thrust, the pilot flying continued to be unaware of the reason for the pilot monitoring's call. This omission was partly due to the lack of any caution or warning, which would come too late anyhow.

The N1 indicator must have shown a decrease, is on FDR!

slowly (Figure 3)

Where are the heading data?

The asymmetric thrust caused the aircraft to suddenly yaw to the right.

he must have seen the deviation of the ground track. He applied tiller, left rudder and differential braking.

The pilot flying had no information and was unaware of the cause of the deviation. As a result, he was surprised and he reacted intuitively. The use of a noise cancelling headset could have played a role.

?? inappropriately.

can only be one cause...

In an attempt to correct the deviation to the right, the pilot flying used nose wheel tiller and rudder pedal steering, as well as differential braking, which is not approved in procedures.

The thrust levers were not immediately retarded to idle. Nor were other standard procedures followed. Such delays and not following trained procedures have been associated with the phenomenon known as the 'startle effect', experienced by both the pilot flying and the pilot monitoring.

No, looking for excuses. This cannot be the case at the beginning of a flight

Throughout the event, the pilot flying used his left hand to operate the tiller while moving his right hand from the throttles to the control wheel, releasing the thrust levers in the process. against the procedures

Because he did not ~~keep~~ his hands on the thrust levers, asymmetric take-off power was engaged for around eight seconds. take proper action

As a result of this continued asymmetric thrust, it became impossible to control the aircraft and the runway excursion became inevitable. + probably never trained n-1 this early in TO

The rejected take-off procedure must be initiated immediately if sudden asymmetric thrust occurs during the take-off roll at low speed.

Each year, crews are trained in rejected take offs at low speed following an engine failure. However, no 'startle effects' will occur during these training sessions as the flight crews know what to expect. ??

There are no certification requirements for situations in which a ~~critical~~ engine becomes inoperative during take-off below V_{MCG} . Wrong. V_{MCG} is published and applies after either engine failure. Procedure (abort) rather than hardware (very large tail). Not a clever finding.

The engine loss of thrust was due to a compressor stall. The cause of the compressor stall remains unknown, although Foreign Object Damage (FOD) and wind turbulence have been excluded. However, the technical state of the engine as found might have contributed to this event.

3.2 Conclusion

1. Engine #4 failed as takeoff thrust was being set.

~~The runway excursion was caused by the pilot's inability to maintain directional control under the conditions of prolonged asymmetric thrust that resulted from the loss of thrust on engine #4 at low speed. The loss of engine thrust was caused by a compressor stall.~~

+ Deeper systemic cause (Annex 13). Pilot training?

Contributing factors

??

The thrust levers were not retarded immediately after the loss of thrust. Such delays and not following trained procedures have been associated with the phenomenon known as the 'startle effect'. doubtful, just after increasing the throttles?

not "inability" to maintain control, because that is not at all possible/ available, but "failure" to close the throttles.

This was the real cause, not a contributing factor.

During training courses in flight simulators, the lessons learned from unexpected situations, such as engine failures, are quite limited as the crews know what to expect. not always

Safety Recommendations for preventing similar incident in the future?
Improve Pilot training (engine failure low speed, real value of V_{MCG}).
Tell Boeing to amend FTCM...

APPENDIX A

TRANSCRIPT

-- of what? CVR? This is a very limited transcript, there must be much more.

From	FDR time (UTC)	Message
Capt	22.33:22	Before taxi checklist
Capt	22.33:42	Three up to down, three up to down, rudder, full left, full right <i>(check of flight controls)</i>
FO	22.34:02	Before taxi checklist, anti-ice
Capt	22.34:04	Anti-ice off
FO	22.34:05	Recall
Capt	22.34:06	Check
FO	22.34:08	Auto brake
Capt	22.34:10	RTO
FO	22.34:11	Flight controls
Capt	22.34:12	Checked
FO	22.34:13	Ground equipment
Capt	22.34:14	Clear
FO	22.34:15	Before taxi checklist completed.
FO	22.34:16	It is very dark
Capt	22.34:18	Ok, OLNO 2Bravo, 160, Runway 21, to initial 60, transition 3000, before take-off checklist
FO	22.34:29	Before take-off checklist, flaps
Capt	22.34:30	20
FO	22.34:31	Take off briefing Is this all of the takeoff briefing? in 3 seconds?
Capt	22.34:32	Review
FO	22.34:33	Upper deck
Capt	22.34:34	Secure
FO	22.34:35	Before take-off checklist completed

From	FDR time (UTC)	Message
Capt	22.34:36	Ok, ready for taxi
FO	22.34:41	Maastricht, Saudia 916 ready for taxi
Capt	22.34:44	Ready
ATC	22.34:46	... 916, to line up and wait Runway 21
FO	22.34:51	Line up and wait Runway 21, Saudia 916
Capt	22.34:54	Clear on the left
FO	22.34:56	Clear on the right
Capt	22.35:02	Only line up, switch light on
Capt	22.35:06	Line up items
FO	22.35:20	Weather left, terrain right
ATC	22.35:35	Saudia 916, Runway 21 , the wind 260 4 knots, you are cleared take off
FO	22.35:40	Cleared take off, Runway 21, Saudia 916
Synthetic voice	22.35:41	Approaching 21
Capt	22.35:45	Have a safe flight
FO	22.35:47	Indeed
Capt	22.35:49	Is the radiofrequency stand by or not?
FO	22.35:51	We did already
Capt	22.35:56	Have a good flight
FO	22.35:58	Have a nice flight
Capt	22.36:14	Do we switch to departure frequency at 2000 feet ?
Synthetic voice	22.36:26	On Runway 21
FO	22.36:31	Set thrust
Capt	22.36:32	Take off
	22.36:33	Sound of engines spinning-up
Capt	22.36:36	Set take-off thrust
	22.36:40	Loud noise (bang)
FO	22.36:41	Off, abort, abort, abort
	22.36:44	Sound of wheels hitting something

From	FDR time (UTC)	Message
Capt	22.36:46	(...) What happened....
	22.36:48	Sound of engines spinning-down
Capt	22.37:00	Switch off the engines
ATC	22.37:08	Saudia 916
FO	22.37:11	Ah, we are out of runway, Saudia 916
ATC	22.37:13	Roger
ATC	22.38:50	Saudia 916, can you give us some information what happened
Capt	22.39:00	We really don't have an idea, after brakes off, then start take off, unable to .. aircraft on the runway, what really happened, I don't know
ATC	22.39:16	Roger, that is copied

ENGINE EXAMINATION

Examination of HPC blades

A borescope inspection carried out on the platform after the occurrence revealed damage to stage 3 and 4 compressor blades in the HPC. Two HPC stage 3 blades (numbers 6 and 7) and two HPC stage 4 blades (numbers 19 and 30) were sent for laboratory examination.

The laboratory examination report indicated that there was no evidence of any relevant impact damage to the stage 3 blades of the HPC. However, it did find that the leading edge tip of blade #6 was missing, due to a fatigue fracture. The high cycle fatigue crack had originated in the tip area and had propagated to the leading edge. While there was no trace of impact damage, there was evidence of tip rub and burr, which may have caused the fatigue in question.

The two HPC stage 4 blades showed damage to their leading edges, both due to impacts originating from the concave side of the airfoil. In blade #30 traces of Ti64 were found in the tip curl, a different alloy from the HPC stage 4 base metal (Ti442).

HPC stages 1, 2 and 3 are made of Ti64, so a fragment of material from these locations could have struck blade #30. In this case, the missing piece of blade #6 could have impacted blade #30. The dented surfaces in the leading edge and the fatigue fracture surface in all of these blades were severely eroded. This could be a result of the position and orientation of these surfaces with respect to the airflow. Moreover, dust trails were found in the dents. It can, therefore, be assumed that this damage occurred many cycles before the engine stall in question. During the previous borescope inspection of engine #4 (on 12 October 2017) the combustor chamber and HPT stages 1 and 2 were inspected.

In summary: the blades that were examined showed no evidence of severe damage. Tip rub resulted in the loss of the leading edge tip of blade #6. Furthermore, all the fractured and dented surfaces were severely eroded, and dust trails were found. Thus, it was concluded that this damage had been caused several cycles before the stall in question, and that such damage solely was not the cause of the compressor stall.

Fan blade examination

During the top case engine tear down, the engine fan inlet and fan blades were subjected to a black-light inspection. Spots of material that may have been organic in nature were

found on two fan blades from engine #4, which were then removed for additional laboratory assessment. That examination found no traces of animal cell material or animal DNA on the fan blades.

VSV and VBV actuator examination

Prior to disassembly, the actuators that drive the Variable Stator Vanes (VSVs) and variable bypass valves (VBVs) were tested. This was because a malfunction of these components could potentially cause a compressor stall.

The VSV actuators showed no obvious damage and were able to travel freely between the 'up' and 'down' positions. These actuators were sent to the engine manufacturer for further testing. A further examination revealed worn rod end bearings of both actuators and worn body bearings of one actuator, which meant that it was not possible to set the stroke of the actuators.

The VBV actuator check showed that the valve was able to travel from the VBV's fully open position to its fully closed position. Its operation was also found to be satisfactory. Additional leakage tests conducted by the manufacturer revealed various leaks of one actuator.

Temperature sensors

Two T12 engine inlet temperature sensors and one T25 compressor inlet temperature sensor were sent to the manufacturer for tests and examination. Two temperature sensors (T12 and T25) were tested. The sensors met the performance requirements but they failed the visual inspection criteria for re-installation, due to corrosion.

Fuel pump

The fuel gear pump was sent to the manufacturer for tests and examination. This fuel pump failed the test and visual inspection, as it was found to have cavitation damage with some bronzing. According to the manufacturer, the pump hardware showed signs that it may have been run without fuel. The fuel pump was scrapped.

Brake system control unit (note: not part of engine but is included here for convenience)

Data from the Brake System Control Unit (BSCU) was downloaded to determine whether any system faults had been reported. Following the downloading and examination of this data, it was found that no faults or anomalies had been recorded.

Bad. Nobody expects this under head Engine Examination.

**Visiting address**

Lange Voorhout 9
2514 EA The Hague
The Netherlands
T +31 (0)70 333 70 00
F +31 (0)70 333 70 77

Postal address

PO Box 95404
2509 CK The Hague
The Netherlands

www.safetyboard.nl